ARTIST'S CONCEPTION OF THE HEADQUARTERS BUILDING

The present building is as originally conceived except for the following:

- a. Lower part of the south end of the building is now convex instead of concave.
- b. Two abrupt curves at the southeast corner are now less sharp.
- c. Front entrance canopy has been separated from the building and is free-standing.
- d. Enclosed passageway between the Headquarters Building and the auditorium is now underground.
- e. None of the ornamental sculpture was used.
- f. The large masses on elevator shafts have been connected and are used for air handling fan rooms.
- g. The kitchen area and two small courts on either side have replaced the passageways to the cafeteria.
- h. Elevated planting areas have replaced the passageway to the auditorium.

This text was used in 011 Bldg Show - 1971 Voult 3-15-1423